To: Williams, Mike[Mike.Williams@tetratech.com]

From: Howell, Tonya

Sent: Mon 10/16/2017 5:45:07 PM

Subject: RE: metals at Des Moines TCE/Dico

| <u>Contaminant</u> | *Media | **Concentrations |
|-----------------------|--------------------|---------------------|
| PCBs | Building Materials | 58,000 μg/kg [max] |
| Dioxins (TCDD) | Building Materials | 114 µg/kg [max] |
| Pesticides (Aldrin) | Building Materials | 520,000 mg/kg [max] |
| Dioxins (TEQ) | SL | 33 ng/kg [max] |
| Pesticides (DDD) | SL | 100,000 μg/kg [max] |
| TCE | SL | 15,000 μg/kg [max] |
| Pesticides (Dieldrin) | SW | 17 mg/kg [max] |
| Pesticides (Aldrin) | ST | 15,000 μg/kg [max] |
| TCE | AR | 92.9 μg/m3 [max] |

Tonya Howell

Remedial Project Manager

Superfund Redevelopment Initiative Coordinator

SUPR/FFPC

913-551-7589

From: Williams, Mike [mailto:Mike.Williams@tetratech.com]

Sent: Friday, October 13, 2017 3:35 PM

To: Howell, Tonya < Howell. Tonya@epa.gov > **Subject:** metals at Des Moines TCE/Dico

Tonya:

| I can give you a really rough number for metals. Based upon soil data collected by Eckenfelder and found in the B&V RI report, there were at least 22 metals detected. Of course, most metals are naturally occurring. However, I noticed at one boring there were some high levels of arsenic, lead, copper and mercury. I didn't compare anything to any published screening criteria. |
|--|
| Does that help at all. If not, I can do some more searching on Monday. I have to leave early today. |
| Thanks, |
| Mike |